- 12. Spare parts for Model 742 and 760 required for 10 years. Some of the present equipment will have to be retained for parts manufacture.
- 13. If the project is to be figured on 1973 plant, updated 5year forecasts by model will be required in December 1969.