

TRAPS - contd.SWEDISH TRAPS

Marketing reported that they did not believe the double arm tournament trap was safe for the trap boy to load.

REDACTED
PRIVILEGED

Also dry cycle testing of the skeet trap uncovered a design fault in the feed mechanism in approximately 4800 cycles. Bearings for the target feed tray are too far from the applied force causing binding and failure. This design is one of those aimed at circumventing Winchester-Western patent claims. Whether or not modifications can be made to eliminate this problem is not known. There is also some question about patent infringement in the design of the target escapement latch.

The possibility of obtaining a license from Olin to use their patented features was discussed.

The meeting adjourned at 11:15 a.m. The next meeting is scheduled to be at Bridgeport on Tuesday, February 22, 1972 at 9 a.m.

JHS:J
Exhibits 1 & 2

Legal advice regarding patent infringement issues.
ATTORNEY CLIENT - WORK PRODUCT

83

REDACTED