(

CENTER FIRE RIFLES - contd.

MODEL 700 BOLT ACTION CENTER FIRE RIFLE - IMPROVEMENTS - contd.

Training of two employees in use of powered hand checkering tools is progressing. Current output of one per day per person is expected to go up quickly. Quality is good. Two more trainees are starting in Custom Repair.

RIM FIRE RIFLES

MODEL 541-S SPORTER BOLT ACTION CLIP MAGAZINE RIM FIRE RIFLE (Introduction 1973)

Production reported that hand checkering of Model 541-S rifle Stocks will continue to permit increased production of Model 3200 shotgun Stocks and Fore-ends. It was recommended that reporting be dropped.

Committee Action:

The Operations Committee agreed to drop reporting on Model 541-S rifles.

MODEL 540X AND 540X-JR POSITION RIFLES
MODEL 40XB STANDARD POSITION RIFLE RIM FIRE
MODEL 40XB RRMY NATIONAL MATCH COURSE RIFLE
(Introduction 1974)

R & D reported that cost estimates and economics have been prepared using sycamore wood. Economics were reviewed - Exhibits and 6.

If standard procedures are used for processing the wood changes, finished drawings are required and will be difficult to obtain for 1974 announcement. Higher priority items are absorbing all design effort. Also, a 7-month lead time is required on wood delivery.