- F. M/788 BOLT HANDLES
- BOLT HANDLE BREAKS OFF FROM BOLT.
- PROBLEM HAS EXISTED SINCE INTRODUCTION.
- IN 1974 ABOUT 450 COMPLAINTS WERE RECEIVED AT ILION.
- A CORRECTION IS NECESSARY TO MAINTAIN THE GROWING POPULARITY OF THE RIFLE.
- G. NYLON 66 DECREASING PROFITS
- FACTORY MARGIN IN JANUARY WAS 37.8% vs. 39.9% AT THE END OF 1971.
- OUR PRICING OPPORTUNITIES ARE LIMITED IN THE FACE OF AGGRESSIVE COMPETITIVE ACTIVITY.