

Broadway Sports Center, Inc.

BROADWAY, VIRGINIA 22815

August 9, 1991

REMINGTON ARMS COMPANY, INC.  
Arms Service Division  
Ilion, NY 13357

Dear Sir or Madam:

The inclosed Remington Model 700 BDL, 30-06 Sprg.  
Serial Number: 6852122 is being returned because when  
pushing the safety from the safe to fire position the  
gun will sometimes fire accidentally.

This firearm was previously forwarded to Clark Brothers  
for repair of the same problem February 2, 1986. However  
customer has indicated that it does not appear that it was  
properly repaired as the same problem exists. The gun  
was not used for a 3 year period after it was supposedly  
repaired due to illness in the family.

Thanking you in advance.

Sincerely,

*Clifford C. Crider*  
Broadway Sports Center, inc.  
112 Mason Street  
P.O. Box 576  
Broadway, VA 22815-0576