

.308, .30-06, & .243

The Committee reviewed the Lonoke Plant audit weighing of the subject ammunition which was under warehouse hold. See Enclosure 1, for details. In addition, the May 11, 1973, letter "Status Report on Center Fire Duplex Loader Improvements" was reviewed. See Enclosure 2.

COMMITTEE ACTION

The Committee approved the actions taken and the procedures initiated by Lonoke Plant to prevent "no powder" or "partial powder charges". Also, the deletion of these ammunition items from the agenda of the Product Safety Sub-Committee was approved.

5mm REMINGTON RIM FIRE MAGNUM


The Committee reviewed the list of wholesalers receiving a case, 2,000 rounds, or more of this item during September and October 1972. This period of shipments followed immediately the loading date on which the two-pound can of wrong powder was used. The results of the Bridgeport Plant audit of returned product was discussed. It appears that a few boxes stamped with the previous day's code, X24D, may have been left over and used early the following day at the start of packaging of Code X25D. Since the recall efforts already undertaken had caused the return of all full-case shipments of Codes X24D and X25D, the Committee discussed the possibility of locating more of these codes by contacting wholesalers that received less than one case shipments. The consensus was that this would be an unproductive effort.

COMMITTEE ACTION

The Committee approved the recommendation that no further action be taken to recall Codes X24D and X25D. The Committee directed that the Production Department instruct both plants to block out the code number, if it does not reflect the correct code date, and stamp the correct code number on the box.

The next meeting will be held at the call of the Chairman.

The meeting adjourned at 4:03 p.m.


T.J. Sharpe
Secretary

TJS/ab
Encl.