

LIMITED DISTRIBUTION

OPERATIONS COMMITTEE
(Product Safety Sub-Committee)

Reference Minute #4 - 1971

R.H. Coleman
P.H. Burdett
J.P. McAndrews
E. Sparre
G.M. Calhoun
R.A. Partnoy

J.H. Hodgson
H.B. Harmon
L.J. Boyle
L.L. Presnell
T.J. Sharpe

Copy No. 34 83

CALIBER 270 CARTRIDGES WITH 130 GRAIN
POINTED SOFT POINT "CORE-LOKT" BULLETS

The Committee met Thursday, November 18, 1971, from 3:06 to 4:02 p.m., to review the recall program to date. It appeared that 129,600 total rounds of all seven codes involved had been shipped to distributors.

As of this date, 41,010 rounds are being held at distributor level. 88,440 rounds have been shipped to dealers by distributors.

There are no personal injuries reported. Six Model 760 rifles are reported damaged and there are possibly five additional rifles also damaged.

Of 260 rounds of code LU031D that have been pulled down at Bridgeport, 14 rounds were 100% #4198 powder and 170 rounds were mixed #4198 and #4350. This is the only code that has been reported to be contaminated.

All damaged guns and seven codes have been requested to be sent to Bridgeport.

The Committee discussed the effectiveness of a public announcement approach to the recall program. It was decided that it would be more confusing than helpful to our efforts.