MINUTE #3 - 1980

Others

E. Preiser

S. McCawley

H. Chisnall

T 💮 Rawson

Callahan

83 $(2)^{n}$

J.

J. c.

Ε.

PRODUCT SAFETY SUBCOMMITTEE MEETING

JUNE 24, 1980

PRESENT:

a Chillenna

1008 ga

Subcommittee

- J. P. Glas, Acting Chairman E. Hooton, Jr.
- E. G. Larson
- R. A. Partnoy, Acting Secretary



Production reported that the 7mm Express Remington ammunition returned with the Remington Model 700 rifle lockup complaint was loaded on the last shift of a load run from August 2 through August 9, 1979. Manufacturing test records indicate that we can isolate the period of contaminated powder in the 7mm Express Remington ammunition to the load run during the period specified above, which included 261,000 loaded rounds. We are attempting to obtain product samples from lots other than M09I, to see if we can further narrow the production lot or lots involved.

The Ilion Plant reports that since August 1979, no other guns have been returned with the complaint that they