

# BARBER - Kinzer PPS GAL RE0000871

RECEIVING AND ESTIMATING REPORT

ORDER  
94-14708

|                        |                    |  |                           |  |                         |           |                           |                   |                                    |
|------------------------|--------------------|--|---------------------------|--|-------------------------|-----------|---------------------------|-------------------|------------------------------------|
| INITIAL<br>FPS         | CUSTOMER ORDER NO. |  | DATE RECEIVED<br>04/29/94 |  | DATE OPENED<br>05/02/94 | DATE CODE | SERIAL NUMBER<br>A6430321 | NEW SERIAL NUMBER | MODEL AND GRADE<br>700 308 WIN BDL |
| ACCESSORIES<br>W/STUDS |                    |  |                           |  |                         |           |                           |                   |                                    |

|       |                                                                    |          |                                                                    |
|-------|--------------------------------------------------------------------|----------|--------------------------------------------------------------------|
| FROM: | CAMPOLI, JOHN M.<br>1753 LEGARE LANE<br>VIRGINIA BEACH<br>VA 23464 | SHIP TO: | CAMPOLI, JOHN M.<br>1753 LEGARE LANE<br>VIRGINIA BEACH<br>VA 23464 |
|-------|--------------------------------------------------------------------|----------|--------------------------------------------------------------------|

CUST NO:096800 CLO.D.

|                                                                                                                                                                                                                                           |                    |                                |                                                                            |           |            |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------|--------------------------------|----------------------------------------------------------------------------|-----------|------------|
| ACCOUNT NUMBER                                                                                                                                                                                                                            | ACCOUNT NUMBER N/C | WRITE <input type="checkbox"/> | SHIP DATE                                                                  | ESTIMATED | VIA<br>UPS |
| GUN CONDITION<br><input type="checkbox"/> NEW<br><input type="checkbox"/> LIGHTLY WORN<br><input type="checkbox"/> WORN<br><input type="checkbox"/> VERY WORN<br><input type="checkbox"/> UNREPAIRABLE<br><input type="checkbox"/> MARRED |                    |                                | REPAIR CHARGE<br>EXCISE<br>TAX<br>INSURANCE<br>UPS<br>PARCEL POST<br>TOTAL |           |            |

| CUSTOMER CONCERN | AMMO | FUNCTION | FINISH | ACCURACY | FIT | INSPECT |
|------------------|------|----------|--------|----------|-----|---------|
| CYCLE            | A1   | R1       |        |          |     |         |
| TRIGGER GROUP    |      | B2       |        |          | E1  | F1      |
| BOLT ASSY.       |      | B3       |        |          | E2  | F2      |
| BARREL ASSY.     |      | B4       |        | D1       | E3  | F3      |
| REC. ASSY.       |      | B5       |        | D2       | E4  | F4      |
| WOOD             |      |          |        | D3       | E5  | F5      |
| METAL            |      |          |        |          |     |         |

MAIN FAULT

*Upon receipt, we could not reproduce the customer concern. However, examination revealed that all 3 trigger adjustment screws have been set. The rear adjustment is out of spec.*

|                      |                                                                                                |
|----------------------|------------------------------------------------------------------------------------------------|
| PARTS                | COMMENTS                                                                                       |
| #32345 Trigger screw | Replace trigger screw & then action at 1/8" manual adjustment. Cost, in question of good work. |
| Chase Credit Card    |                                                                                                |
| 4800 1206 3200 4164  |                                                                                                |
| Spd 5/3/95           |                                                                                                |
| Phone 804-479-1460   |                                                                                                |

|                |       |       |      |        |         |
|----------------|-------|-------|------|--------|---------|
| REPAIRMAN      | PROOF | CLEAN | TEST | TARGET | PATTERN |
| GALLERY TESTER | DATE  | DATE  | DATE | DATE   | DATE    |

OFFICE COPY

RD6925 REV. 1/94