

endurance1000rd.txt

From: Reesor, Phillip K.
Sent: Sunday, September 17, 2000 9:20 AM
To: Franz, Scott
Cc: Arnold, Jesse T.; Lee, Robert
Subject: endurance

Scott, during the 1000 rd. level clean & inspect the bolt handle broke off of gun B-14,
I instructed Bob & Jesse to replace it with B-17 for the extended endurance test. B-17
to B-20 were not scheduled to be tested any further than 1000 rds. or involved in any other additional testing.

PKR

CONFIDENTIAL 83

Page 1

ET07296