

CEIVING AND ESTIMATING REPORT			COMMENTS			ORDER R 92-27164		
CUSTOMER ORDER NO. 118362			ATTN ED JOY					
RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE			
107/92	12/11/92	DK 9-90	B6886666		700 243		FS	
SSORIES		W/STUDS		SCOPE BASE		L/SIGHTS		

SHIP TO:		SHIP TO:	
DENNIS HARDWARE 1 GRAVOIS RD FENTON	NO 63026	DENNIS HARDWARE 1 GRAVOIS RD FENTON	MO 63026

CUST NO: 003106 IDION			
UNIT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST
CONDITION		PROM. DATE	ESTIMATED
EW			12/11/92
IGHTLY WORN			
JORN			
ERY WORN			
INREPAIRABLE			
IARRED			
		VIA	UPS
		REPAIR CHARGE	25.00
		EXCISE	
		TAX	
		INSURANCE	
		UPS	
		PARCEL POST	
		TOTAL	

TOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
E	A1	B3			E1	F1
GER GROUP		B3			E2	F2
ASSY.		B4		D1	E3	F3
REL ASSY.		B5		D2	E4	F4
ASSY.				D3	E5	F5
JD			C1			
AL			C2			

Unable to duplicate customer concern.
 Examination revealed trigger assembly adjusted out of factory
 for the front 21 trigger housing from removing adjustment screw
 contact. Trigger Pull 3 1/2 lbs

S		COMMENTS	
30 Sept 01		Trigger trigger assembly complete at 1/2 normal replacement cost, as part of good will	
Allen Wilton			
→ go ahead per Ken Bates phone 3/1			
REPAIRMAN	PROOF	CLEAN	TEST
122			
GALLERY TESTER	DATE	DATE	DATE

OFFICE COPY

RD6L