BARBER - 5.22.06r0001566

deker, Jim

rom:

Franz, Scott

Sent:

Wednesday, November 22, 2000 3:01 PM

To:

Bristol, II Ronald H.; Russo, Al; Trull, John C.; Golemboski, Matt R.; Zajk, Joseph J; Diaz,

Danny, Keeney, Mike; Danner, Dale; Snedeker, Jim; Reesor, Phillip K.; Franz, Scott

Subject:

T & P Conf. Call Topics

Importance:

High

Disregard earlier e-mail. The following topics will be discussed at 4:00 pm.

- Schedule update
- Part breakages:

Bolt stop - 1 failure @ 29 rds.

Bolt handle - 3 failures

1 during normal shooting @ 79 rds.

2 during abusive slam test - test stopped

- Extractor sticking 1 gun @ 28 rds.
- SAAMI drop test on hold, can't adjust triggers to process minimum
- Grip caps falling out 13 of 29
- · Take down screws loose confirms what Mayfield has seen
- Bracket screws loose
- Followers binding 11 boxes, ranged in rds. from 11 to 87 rds.
- Bore sight results not as good as last test
- The "worst" case sample for trigger position, side to side, was sent to Mark's attention Tuesday. T & P is now a 29 gun test
- Scopes have not yet been sent to Al Russo: Will go out either today or Monday.

NOTE: Topics in red are new.



ET07398