Remington.

## OUPIND

## **REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS AMMUNITION TARGETS TRAPS

TELEPHONE (315) 894-9961

August 17, 1988

Mr. Paul F. Edwards 6409 E. Fairfield Mesa, Arizona 85205

Dear Mr. Edwards:

This is in reply to your letter of July 31, 1988.

Since the late 1970's, there has been a Model 600 Series Recall in effect to replace trigger assemblies.

In order to update your Mohawk 600, serial number A6252163, please ship it, <u>via</u> United Parcel Service, Transportation C.O.D., to:

> Remington Arms Co., Inc. Model 600 Series Recall Arms Service Division 14 Hoefler Ave. Ilion, NY 13357

Upon receipt of the rifle, our Service Division will, at no charge, install a new trigger assembly. The firearm will then be returned to your home address, freight prepaid.

We trust this information will be helpful to you, Mr. Edwards, and we wish you every hunting and shooting success.

Sincerely,

R.H. Potter Specialist Product Service

RHP/nb