

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-27321

INITIAL	CUSTOMER ORDER NO.		SERIAL NUMBER		NEW SERIAL NUMBER		MODEL AND GRADE	
FPS	4804		6576755				700 30-06- ADL	
DATE RECEIVED	DATE OPENED	DATE CODE						
12/06/93	12/14/93	OW 7-72						
ACCESSORIES		W/STUDS		W/SWIVELS		SCOPE BASE		L/SIGHTS

FROM:	SHIP TO:
<i>J. Smith</i> EWELL CROSS GUN SHOP 8240 I-30 WEST FT WORTH TX 76108	EWELL CROSS GUN SHOP 8240 I-30 WEST FT WORTH TX 76108

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA
				1-10-94	UPS

GUN CONDITION	REPAIR CHARGE
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED	25
EXCISE TAX INSURANCE UPS PARCEL POST TOTAL	

Product Service

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5			E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

Letter only 1972, upon receipt, unable to duplicate Customer Concern. However, cause of complaint was important. The first step, a and gun safety can now work in slightly. Examination revealed the action and trigger assembly in correct with dirt, and a heavy, sticky substance. Rifle has been fully maintained. Trigger adjustment has been reset, and not removed from adjusting screw.

Before complete trigger and and clean action at 12 normal replacement cost, is greater of good use

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTE
CC					
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV.