

Art Long

P.I. NO GUN EXAMINATION REPORT NUMBER: _____ MODEL: 700 BDL
GENERAL CONDITION: GOOD R #: 023941
OUTSIDE WORK: ALL TRIGGER ADJUSTING DATE: 11-16-72
SCREWS WITHOUT SEAL. FROM: CHARLES W. FISHER
FIRED AMMO TYPE: REMINGTON COLUMBUS, OHIO
& CONDITION: _____ GUN #: 6418265
PROOF: R.E.P.-1 ASSEMBLER 13 INSP.: 9 TEST: 13 CODE: AV=3/71
HEADING: O.K. GA./CAL.: 17 REM.
BREECH OPENING: - CHECKED BY: C. PROSSER
RECOIL SHOULDERS: O.K. APPROVED: _____
CHAMBER: O.K. APPROVED: _____
TEST: 20 ROUNDS NO PRIMER PIERCING APPROVED: _____
AFTER SWAGING FIRING PIN HOLE. APPROVED: _____
COMPONENT CONDITION: (Damaged, Broken, Old Style)

TRIGGER STOP AND ENGAGEMENT SCREWS OUT OF ADJUST-
MENT. FIRING PIN HOLE NOT SWAGED. SEAR AND TRIG-
GER CONNECTOR DAMAGED.

COMPLAINT: PIERCES PRIMERS, FIRES CLOSING BOLT.

INCIDENT: FOLLOW DOWN

COMMENTS: PRIMER PIERCING CAUSED DAMAGE TO THE
CORNERS OF THE SEAR AND TRIGGER CONNECTOR,
RESULTING IN FOLLOW DOWN.