

TLW 03001

11-16-06

TLU 0300Au

m/710

Engagement

Spear Lift

| Sample | Ser. No. | 1 | 2 | 3 | 4 | GAP | 1 | 2 | 3 |
|--------|----------|-------------|-------|-------|-------|-------|-------|-------|--------|
| B-1 | 71001124 | .0297 | .0298 | .0288 | .0315 | .003 | .0122 | .0139 | .0133 |
| B-2 | 71001184 | .0277 | .0278 | .0268 | .0301 | .0037 | .0127 | .0132 | .0131 |
| B-3 | 71001244 | .0282 | .0291 | .0272 | .033 | .0049 | .015 | .0145 | .0147 |
| B-4 | 71001288 | .032 | .0311 | .0307 | .0345 | 0 | .0151 | .0173 | .0167 |
| B-5 | 71001421 | .0268 | .027 | .026 | .0291 | .0008 | .0134 | .0123 | .0113 |
| B-6 | 71001462 | .0262 | .0261 | .0259 | .0297 | .0025 | .012 | .0124 | .0121 |
| B-7 | 71001504 | .0294 | .0299 | .0294 | .0328 | .0038 | .0154 | .0139 | .0136 |
| B-8 | 71001511 | out of test | | | | | | | |
| B-9 | 71001524 | .0265 | .0267 | .0281 | .0297 | .0007 | .0138 | .0132 | .0145 |
| B-10 | 71001529 | .0287 | .0283 | .0302 | .0302 | 0 | .0123 | .0141 | .0141 |
| B-11 | 71001534 | .0311 | .031 | .0306 | .033 | .0026 | .0141 | .0137 | .0131 |
| B-12 | 71001535 | .0273 | .0283 | .0286 | .0309 | .0023 | .0144 | .0137 | .013 |
| B-13 | 71001539 | .0291 | .0295 | .0299 | .0329 | .0017 | .0152 | .0143 | .0146 |
| B-14 | 71001559 | .0314 | .0308 | .0315 | .0352 | .0032 | .013 | .0126 | .0149 |
| B-15 | 71001578 | .029 | .0279 | .0293 | .032 | .0026 | .0162 | .0163 | .01583 |
| B-16 | 71001580 | .0307 | .0304 | .0313 | .0334 | .0043 | .0156 | .0161 | .0158 |
| B-17 | 71001583 | .0360 | .0375 | .0366 | .0412 | 0 | .0137 | .0135 | .0137 |
| B-18 | 71001584 | .0291 | .0272 | .0286 | .0282 | .0026 | .014 | .0138 | .0138 |
| B-19 | 71001595 | .0286 | .0282 | .0286 | .0312 | .0021 | .019 | .0119 | .011 |
| B-20 | 71001605 | .0262 | .0271 | .026 | .0318 | .0024 | .0125 | .0153 | .0165 |
| B-21 | 71001613 | .0256 | .0256 | .0251 | .029 | 0 | .0151 | .0146 | .0145 |
| B-22 | 71001623 | .0271 | .0273 | .0262 | .0297 | .004 | .0134 | .0134 | .0144 |
| B-23 | 71001632 | .0267 | .0271 | .0278 | .0296 | .0011 | .0126 | .015 | .0157 |
| B-24 | 71001634 | .0279 | .0278 | .0288 | .0334 | 0 | .0145 | .0141 | .0149 |
| B-25 | 71001643 | .0301 | .0304 | .0312 | .0308 | .0018 | .0156 | .013 | .0149 |
| B-26 | 71001647 | .0269 | .0285 | .0292 | .0296 | .0014 | .0129 | .0138 | .0135 |
| B-27 | 71001724 | .0298 | .0304 | .0299 | .0315 | .0017 | .0163 | .0173 | .0175 |
| B-28 | 71001760 | .0344 | .0336 | .0367 | .0381 | 0 | .0171 | .0127 | .0149 |
| B-29 | 71001782 | .0284 | .0293 | .0303 | .0302 | 0 | .0162 | .0154 | .0157 |
| B-30 | 71001789 | .0284 | .0285 | .0307 | .0322 | .0019 | .0128 | .0138 | .0131 |

Note:

- * measured engagement at 20x magnification
- * B-5 missing rear takedown screw
- * Stock screws are not torqued

ET07523