

*Remington.*



**REMINGTON ARMS COMPANY, INC.**

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

March 31, 1987

Mr. Douglas Hamann  
5551 Townline Rd.  
Wisconsin Rapids, WI 54494

Dear Mr. Hamann:

Your letter of March 6, 1987 that was addressed to our Bridgeport, Ct facility, regarding the accidental firings you have experienced with your Model 700 ADL 270 Win caliber rifle, has been forwarded to this office for handling.

We were indeed sorry to learn of your having problems of any kind with one of our products.

Generally, the type of problem you described results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or from inadvertent contact with the trigger while the safety is in the "fire" position.

Please, at your convenience, return the rifle via U.P.S. insured to:

Remington Arms Company, Inc.  
14 Hoefler Ave  
Ilion, NY 13357  
Attn: J. A. Stekl, Supervisor  
Product Service

Be sure to boldly mark the two (2) butt ends of the outside of the package "STEKL" to expedite handling.

Upon receipt, the rifle will be thoroughly inspected and if it is found to be factory faulty, we will gladly make any necessary corrections on a no-charge basis.