


KEIDEL'S
Gunsmithing Service



927 Jefferson Avenue
Washington, Pennsylvania
15301

(412) 222-6379

DEAR FRED,

IN CASE YOU CAN NOT READ THIS CLAIM FORM 24704, THE TRIGGER WOULD NOT RESET AFTER BEING PULLED. WE FEEL THAT THIS CONDITION WAS MOST LIKELY CAUSED BY RUST BECAUSE THERE IS SOME EVIDENCE ON THE TRIGGER ITSELF. I AM SENDING IT TO YOU FOR INSPECTION JUST IN CASE.

THE RIFLE HAD BEEN PURCHASED THE SAME WEEK WE SERVICED IT.

SINCERELY,
Bruce Keidel