

Remington.



REMINGTON ARMS COMPANY, INC.

SPORTING ARMS-AMMUNITION-TARGETS-TRAPS

ILION, NEW YORK 13357

TELEPHONE (315) 894-9961

January 22, 1988

Mr. Homer L. Layne, Jr.
Rt1, Box 465
Pelham, Tennessee 37366

Dear Mr. Layne:

Your letter of January 5, 1988 regarding the accidental discharge, and subsequent truck damage, of your Remington Model 700 rifle, serial number A6693624, has been forwarded to this office for handling.

We were indeed sorry to learn of your having a problem of the nature you describe.

Generally, the type of problem you describe results from either improper adjustment of the trigger assembly outside our factory, from improper maintenance of the rifle, or from inadvertent contact with the trigger when the safety was in the "fire" position.

Please, at your convenience, return the rifle via UPS, transportation C.O.D. to:

Remington Arms Co., Inc.
Attn: R.L. St. John, Product Service
14 Hoefler Ave.
Ilion, N.Y. 13357

Be sure to mark the two (2) ends of the outside of the package "ST. JOHN" to expedite handling.