November 20, 1987

Remmington Arms Company, Inc. Product Service Dept. Attn: Roger Potter 14 Hoefler Ave. Ilion, NY 13357

RE: Roger Potter

I am returning my rifle as requested.

Just a note to describe what the concern is:

In 1985 I returned my gun for repair. The problem at the time was the gun would occasionally fire on release of the safety. Finally reaching the point where upon closing the bolt the gun would fire. The gun was repaired with a new trigger assembly, supposedly fixing the problem. However on November 16, 1987 upon attempting to unload my rifle and releasing the safety, the gun fired almost shooting a hole in my foot.

At this point I feel that I would never feel comfortable using this rifle and I feel tha my rifle should be replaced.

Thank you.

Sincerely

Aug or

Stephen McNeil RD 1, Box 343

Perkinsville, VT 05151

802-263-5275 (home) 802-885-5118 (work)