

Box 155
Dodd City, Tex. 75438
January 9, 1979

Re: Rifle discharged when taken off safety.
Model 270
Series 700 Ser. no. 6524970

Remington Arms Service Division
Ilion, New York 13357

Dear Remington Arms Representative,

In late November of 1978, a lady in your office whom I talked to about the enclosed rifle, advised me to send the rifle to you with a letter explaining what had happened.

I had been deer hunting and had returned to camp with the rifle beside me on the seat with the barrel pointing to the floor. I reached down to take it off of safety to unload it, and the rifle discharged, shooting a hole through the floor of the pickup.

I decided to wait until after the holidays to send the rifle in because of the heavy mail load.

Sincerely,
Johnnie L. Mills
Johnnie L. Mills