

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER 1

R 91-23830

INITIAL	CUSTOMER ORDER NO.				
FPS	A80794				
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/18/91	11/21/91	WZ 8-75	6893013	1	700 30-06 BDL
ACCESSORIES	W/STUDS SCOPE BASE L/REAR SIGHT				

FROM:

SHIP TO:

MOORHEAD SCHEELS
505 CENTER AVE
MOORHEAD
USA

MN 56560

MOORHEAD SCHEELS
505 CENTER AVE
MOORHEAD
USA

56560

CUST NO: 014820 C.O.D L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST	PROM. DATE	ESTIMATED 11-26-91	VIA UPS
GUN CONDITION					REPAIR CHARGE	
☐ NEW					EXCISE	
☐ LIGHTLY WORN					TAX	
☐ WORN					INSURANCE	
☐ VERY WORN					UPS	
☐ UNREPAIRABLE	PARCEL POST		TOTAL			

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	"Rifle discharged unintentionally, causing approx. 700¢ worth of damage ^{B2} to the transmission of a truck. Before discharge, bolt worked very hard customer tried to open bolt ² unsuccessful, upon closing bolt, rifle discharged."					
TRIGGER GROUP						
BOLT ASSY.						
BARREL ASSY.						
REC. ASSY.						
WOOD	B5		D2	E4	F4	
METAL		C1	D3	E5	F5	

MAIN FAULT

MAIN FAULT No fault found - rifle operates properly in every respect. Many attempts were made to capture the shift to fire upon closing the bolt, but it would not malfunction.
Tagger pull 5 pounds; rear - left .0085"

PARTS	COMMENTS	REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
	Gifts can be returned as-is, or, if it will better restore confidence in the gun, we can install a new trigger assembly at a nominal cost, as a gesture of good-will.	DE					
		GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

BD6925 REV. 8/91