

RECEIVING AND ESTIMATING REPORT

INITIAL		CUSTOMER ORDER NO.		COMMENTS	
LCS		6755		ATTN: JIM STEKLER W/ 416 TAYLOR BLVD REPORTED STOCK NOT OF OUR MANUFACTURE	
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	MODEL AND GRADE	ORDER
06/12/90	06/21/90		A5381341	700 416	R 90-1972
ACCESSORIES		SCOPE BASE			
FROM:			SHIP TO:		
RED'S GUNSMITHING 1230 EAST 60TH AVE SUITE 102 ANCHORAGE AK 99518			RED'S GUNSMITHING 1230 EAST 60TH AVE SUITE 102 ANCHORAGE AK 99518		
ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE	PROM. DATE	ESTIMATED	VIA
					UPS
REPAIR CHARGE					
TAX					
INSURANCE					
UPS					
PARCEL POST					
TOTAL					
GUN CONDITION:					
☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED					
CUSTOMER'S REQUEST					
MAIN FAULT					
PARTS					
<i>Trigger assembly has been replaced by product service.</i> <i>Return ship to sender</i> <i>Charge 1/2 normal price for trigger assembly</i> <i>Work Done</i>					
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

RD6925 REV. 6/88