

## RECEIVING AND ESTIMATING REPORT

CUST NO:046572 ILION				COMMENTS WEATHERBY			
INITIAL LCS	CUSTOMER ORDER NO.						
DATE RECEIVED 07/18/91	DATE OPENED 07/23/91	DATE CODE AK 3-90	SERIAL NUMBER C6521887	MODEL AND GRADE 700 300 AS/MAG		ORDER R 91-1431	
ACCESSORIES W/STUDS		L/SIGHTS					

FROM:

RODGERS, TERRY  
RT 2 BOX 531B  
LA FAYETTE  
USA

GA 30728

SHIP TO:

RODGERS, TERRY  
RT 2 BOX 531B  
LA FAYETTE  
USA

GA  
30728

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE <input type="checkbox"/>	CLEAN/TEST	PROM. DATE	ESTIMATED 8-9-91	VIA UPS
----------------	--------------------	--------------------------------	------------	------------	---------------------	------------

REPAIR CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
---------------	-----	-----------	-----	-------------	-------

**GUN CONDITION:**

NEW

☐ SLIGHTLY WORN

☐ VERY WORN

☐ MISUSED

☐ MARRED

### CUSTOMER'S REQUEST

Firing pin falls when you close bolt, sometimes when you push safety off.

### MAIN FAULT

MAIN FAULT  
Tugpin assembly rusted from unknown source - internal parts of assembly are not moving freely - rftl would not work as receiver.

PARTS		REPAIRMAN				
1) replace trigger assembly at no-charge, as gesture of good-will. - 4 rounds per round. 2) Have rifle shot in gallery to check for accuracy.		DE GALLERY TESTER		PROOF	CLEAN	TEST
		DATE	DATE	DATE	TARGET	PATTERN

OFFICE COPY

RD6925 REV. 7/90