

End Supp

RECEIVING AND ESTIMATING REPORT						COMMENTS		ORDER #	
INITIAL		CUSTOMER ORDER NO.						R 94-11507	
FJB									
DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE				
03/30/94	03/31/94	PU 6-71	64483		700 30-06 BDL				
ACCESSORIES		SCOPE BASE		SIGHTS					
FROM:		SHIP TO:							
SPANGLER, JAMES J C GREEN & SONS INC 122 WEST MAIN ST THOMASVILLE		SPANGLER, JAMES J C GREEN & SONS INC 122 WEST MAIN ST THOMASVILLE				NC 27360			
L		COST NO: 05189 C.O.D.L.							
ACCOUNT NUMBER		ACCOUNT NUMBER NC		FROM DATE		ESTIMATED		VIA	
								UPS	
GUN CONDITION						REPAIR CHARGE			
☐ NEW ☐ LIGHTLY WORN ☐ WORN ☐ VERY WORN ☐ UNREPAIRABLE ☐ MARRED						EXCISE TAX INSURANCE UPS PARCEL POST TOTAL			
CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT			
CYCLE	A1	gun types which close	3.6						
TRIGGER GROUP		B2			E1	F1			
BOLT ASSY.		B3			E2	F2			
BARREL ASSY.		B4		D1	E3	F3			
REC. ASSY.		B5		D2	E4	F4			
WOOD			C1	D3	E5	F5			
METAL			C2						
MAIN FAULT <i>Upon receipt, we were made to understand the customer concern, however, information provided that the trigger adjustment was trigger stop screw loose from set. The trigger stop screw was tightened and a gunsmithing shop substituted. Rifle now 14 ft and good shooting.</i>									
PARTS					COMMENTS				
<i>Trig Part - 4.00 Gun Part - 0.00 #26345 Trigger Group N/S no left lock Customer request</i>					<i>Explosive completed trigger assembly and when action was 1/2 normal replacement. No gas or good work. Go ahead</i>				
REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN				
F3									
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE				

OFFICE COPY

RD925 REV. 1/94