

properly and any dirt or oil not let accumulate in or on the trigger assembly, as this condition could adversely affect the operation of the trigger assembly.

As a gesture of good-will, and to insure that faith in the rifle is restored, we will install a new trigger assembly at no charge. However, a service charge will be applied for cleaning the action.

Thank you for affording us this opportunity to be of service, and we trust our action meets with your approval.

Sincerely,



D. J. Zanita, Specialist
Product Service

DJS:tpp