

RECEIVING AND ESTIMATING REPORT

CUST NO: 048532 C.O.D		COMMENTS ATTN J STEKL W/WILLIAMS REAR SIGHT	
CUSTOMER ORDER NO.			
RECEIVED 03/91	DATE OPENED 09/04/91	DATE CODE OR 7-68	SERIAL NUMBER 118833
MODEL AND GRADE 660 350REM		MAG	
ORDER R 91-17410			
SERIES SCOPE BASE			

SHIP TO: STOKLEY, MIDGE P O BOX 792 (1 MILE HAINES HWY) HAINES USA AK 99827		SHIP TO: STOKLEY, MIDGE P O BOX 792 (1 MILE HAINES HWY) HAINES USA AK 99827	
NT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	CLEAN/TEST
PROM. DATE	ESTIMATED	VIA UPS	

CHARGE	TAX	INSURANCE	UPS	PARCEL POST	TOTAL
CONDITION: ☐ NEW ☐ SLIGHTLY WORN ☐ VERY WORN ☐ MISUSED ☐ MARRED VER'S REQUEST					

"...after... the rifle safety was released".

Customer's complaint: Disassembly of rifle blocked the following:
1) Trigger assembly of rifle, to below Chamber for open (2 3/4 inch), as a
result trigger was not positive. 2) Firing pin and spring mechanism
is blocked with oil. 3) Trigger assembly is contaminated with excessive lubrication
oil, which with cold temperatures could cause a problem.

1) replace the trigger assembly per m/p 660
Beast N/C

2) Clean firing pin assembly

REPAIRMAN	PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE