

RECEIVING AND ESTIMATING REPORT			COMMENTS		ORDER R92-17175
INITIAL FPS	CUSTOMER ORDER NO.		ATTN: JIM STEKL W/BTM OF SCOPE MNTS		
DATE RECEIVED 08/27/92	DATE OPENED 08/27/92	DATE CODE LJ 2-89	SERIAL NUMBER C6340090	NEW SERIAL NUMBER	MODEL AND GRADE 700 270 WIN MNT
ACCESSORIES W/STUDS		SCOPE BASE			

FROM: VELLUTINI, AL
281 MONTE VISTA AVE
HEALDSBURG, CA 95448

SHIP TO: VELLUTINI, AL
281 MONTE VISTA AVE
HEALDSBURG, CA 95448

CUST NO: 065457 C.O.D L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☒	CLEAN/TEST	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------	---	------------	------------	-----------	------------

UN CONDITION	REPAIR CHARGE
☐ NEW	EXCISE
☐ LIGHTLY WORN	TAX
☐ WORN	INSURANCE
☐ VERY WORN	UPS
☐ UNREPAIRABLE	PARCEL POST
☐ MARRED	TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
TRIGGER	A1	B1				
TRIGGER GROUP		B2				
TRIGGER ASSY.		B3			E2	F2
TRIGGER ASSY.		B4		D1	E3	F3
TRIGGER ASSY.		B5		D2	E4	F4
TRIGGER			C1	D3	E5	F5
TRIGGER			C2			

NO FAULT. Could not duplicate above complaint, however, the trigger
operation is suspect about and sluggish - investigation
revealed issue of trigger assembly. The trigger assembly
has been replaced and the trigger will now function
properly. This condition could cause the malfunction
reported.

Trigger pull 5 1/2 pounds 9 o'clock. 8/13/92

REPAIRMAN		PROOF	CLEAN	TEST	TARGET	PATTERN
GALLERY TESTER		DATE	DATE	DATE	DATE	DATE