


Since we found the trigger assembly to be inoperative, we can either re-adjust the present assembly or, if it will better restore confidence in the rifle, we will install a new trigger assembly at no-charge as a gesture of good-will (either option is subject to a \$10.00 handling plus return shipping fee). We will await the decision and reply.

Thank you for affording us the opportunity to examine the rifle and report our findings.

Sincerely,



J.A. Stekl, Specialist
Product Service

JAS: tpp