

SWIFT, KENNEDY & CO. — SWIFT KENNEDY FINANCIAL CO.

994 Beaver Drive  
P.O. Box 1032  
DuBois, PA 15801  
814-371-5270  
FAX 814-371-2898



Insurance With Integrity  
SINCE 1921

682 Main Street  
P.O. Box E  
Brockway, PA 15824  
814-268-3103

March 21, 1994

Remington Arms Co., Inc.  
Bridgeport, Connecticut 06602

Dear Sirs:


I just watched "60 Minutes", a segment on guns and safety. The Remington Model 700 was sighted as having a safety problem. I want to show an incident that happened to me three years ago at hunting camp. An incident that I have taken responsibility for, an incident that strained a friendship, and an incident that has kept a friend from hunting camp. I will describe the incident as best I can remember.

It began while teaching the younger members of camp a safe way of unloading a weapon. After removing live ammo through the floor plate, I released the safety to remove the live shell in the chamber. When the safety was released the remaining shell was fired. There were five shocked and frightened people.

What can be done to prevent this? I have not had a repeat experience; however, if there is a safety problem and a way to fix it, I want to know.

Sincerely,

*Stephen R. Volpe*  
Stephen R. Volpe



PRODUCT: \_\_\_\_\_  
CALIBER: \_\_\_\_\_

CUSTOMER'S ATT \_\_\_\_\_

BEGINNING: \_\_\_\_\_

AT END: \_\_\_\_\_

CUSTOMER CC \_\_\_\_\_

RESOLI \_\_\_\_\_

CC \_\_\_\_\_

AUTO • BUSINESS • HOME  
FIRE • LIABILITY • BONDS



LIFE • PENSIONS • IRA'S  
HEALTH • EMPLOYEE BENEFITS