PrintDis		inzer PPS C	GAL RE 000	587 Remington Arms Co., J	Ínc.					Page 1 of 2				
			-	Product Service										
				Legal Case #:5244										
Case Info	ormation													
RE#	Date Oper	ned Da	te Opened(PS) 11/30/2010	Date Closed	Inciden	t Date	Pr	e Lit	Lit	Obsolete				
Custome	r Informatio	n												
Туре	Business	First Name	Last Name	Street	City	State	Zip	Age	С	Contact				
Incident		Mark	Fjone	5223 E. Aire Libre	Scottsdale	AZ	85254		H 602	2-385-1253				
Incident Information														
	Claims			Codes		epair Est.		edical atmen	t	Medical Status				
ΡI														
PD	PD Cause:4079 Other - Unexamined													
- Fired	l when touch	ning Comment	Unexpla	ined Discharge - No M	lention		Un	Fired when touching Concernations Unexplained Discharge - No Mention Unknown						

S Fired when touching the safety Concern:1025 Unexplained Discharge - No Mention of Safety Position

С

11/30/10 Per call from Mark, he has 5 Model 700's and 2 Model 600's. One of the 700's fired when he touched the safety and was sent to the factory for repair. The trigger was replaced in 2007, repair # 125620. The trigger screws had been altered. He would like all the rifle inspected for safety since he bought them all 2nd hand. I recommended Vang Comp in AZ for the 700's and offered prepaid labels for the obsolete 600's to come to the factory.cm

Firearm Info M Remin Date Pu	fg. ngton	Ty CF/ Where Pi	BA	Mode 600 Access)/	Orig	SKU n/a inal Owner N	Serial	Bbl.	DOM
Mf Remin Date Pu	ngton	Ty CF/ Where Pu	BA	Mode 60 Access	D/	Orig	SKU n/a inal Owner N	Serial	Bbl.	DOM
Other Produce Settlement Settlement	cts Informatic Release of Repair/Rep Cos	lacement	ned Rer Release D Repair/Replac Date	ate	00/CF/BA Reimburse	ment	Cash Settlement	Reim. Da APV	te Ci	ash Date APV
Examination	[Remington/(CF/BA]								
Part		Sub-	Part		Code			Commen	t	
Examination	[Remington/(/30/2010

•

BARBER - Kinzer PPS GAL RE 0009587

•	PrintDisplay	(inzer PPS GAL RE 0009588		Page 2 of	of 2
1	DARDER - r	VIIIZEI PPS GAL RE 0009500		1	
•	Part	Sub-Part	Code	Comment	

4

http://cps03ap13:200/psaapp/PrintDisplay.aspx?ID=5244&Type=Case

11/30/2010

BARBER - Kinzer PPS GAL RE 0009588

PS 11476

BARBER - Kinzer PPS GAL RE 0009589

Ŋ

,	Case #	5244	Date of Cal	11/30/10	Date of		PreLit Lit	Obs	
(Reporter name address				Incident Name/Age address	Ma Sa	irk Fjo 73 E. 1	me fire Li	bre
	contact #'s				contact #'s	Scotts 605	17K Fjo 23 E. 1 dale / 2-385-1	253	254
	email	I			email				
	Injury Medical Treatment						·		
	Alleged cause								
	Firearm 700	Ser #	Cal	DOM	Orig owner?	When/W	here purchased		
()	Ammunition	Factory/Reload	Manuf	Caliber	Buliet type/wgt	Lot #	Additional info		
	Other Product								
	old style trigger 2007 125620 I had issue - touch safety of gun went off twice son-in-law was handling.						rice		
	Notes:	5×700 2×600	All	2nd					
	Customer's Request		116399	93					
(My actions/	2xb	sxe5	Эх	. ARS	1			

Remington.

www.remington.com

А

Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

2.1

ARS LABEL REQUEST FORM

DATE:	11/30/2010	REQUESTED BY:	christy
QUANTITY:	/	WEIGHT PER PACKAGE:	10
PLEASE CHECK ONES	/ 01		
MEDIA			i
COORDINATOR			xxx
TO MAIL		I WILL MAIL	
DESCRIPTION:			
	2 x Model-600 rifles		
	the rist O laboalt		
	print 2 labes!		
			·····
		INFORMATION	
	LADEL		
			
MAIL LABEL TO:	Mark Fjome		
	5223 E. Aire Libre		
	Scottsdale, AZ 85254		
• •			
RETURN ITEM TO:	Rem Product Service	<u> </u>	

TRUEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATOR

4XX596 DEC 1, 2010 ALL CURR USD 1 OF 1 SVC GNDCOM ACT UT 10.0 LBS TRACKING# 1Z4XX5969066335223 REF 1:MARK FJOME/CD/CM REF 2:600 RIFLE	4XX596 DEC 1, 2010 ALL CURR USD 1 OF 1 SVC GNDCOM ACT WT 10.0 LBS TRACKING# 1Z4XX5969066685613 REF 1:MARK FJOME/CD/CM REF 2:600 RIFLE HANDLING CHARGE 0.00
HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 COD 0.00 RS 0.50 DV 0.00 DGD 0.00 SD 0.00 DC 0.00 DGD 0.00 SD 0.00 AH 0.00 PR 0.00 SP 0.00 TOT PUB CHG 11.74 PUB+HANDLING 11.74	SINGLE-PIECE PUB RATE CHRGS: SVC T/P USD DV 0.00 COD 0.00 RS 0.50 DC 0.00 DGD 0.00 SD 0.00 AH 0.00 PR 0.00 SP 0.00 TOT PUB CHG 11.74 PUB+HANDLING 11.74