

GUN # - XC 1054
 DATE - 5-20-99
 SHOOTER - JH

M/710 EET SAMPLE RIFLES
 100 ROUND PROOF TEST

TRACKING # TLW 9142G
 PROJECT # 241095

AMMO	REM	PRF 30-06	LOT #	F21G C0526
		MALFUNCTIONS	INS.	MALFUNCTIONS
1	1	HEADSPACE MIN + .003	✓	51 1
2	2	HEADSPACE .003	✓	52 2
3	3	HEADSPACE .003	✓	53 3
4	4	HEADSPACE .003	✓	54 4
5	5	HEADSPACE Missfire .003	✓	55 5
6	6	HEADSPACE .003	✓	56 6
7	7	HEADSPACE .003	✓	57 7
8	8	HEADSPACE .003	✓	58 8
9	9	HEADSPACE .003	✓	59 9
10	10	HEADSPACE ✓ .003	✓	60 10 ✓
11	1			61 1
12	2			62 2
13	3			63 3
14	4			64 4
15	5	Missfire		65 5
16	6			66 6
17	7			67 7
18	8			68 8
19	9			69 9
20	10	HEADSPACE ✓ .004	✓	70 10 ✓
21	1			71 1
22	2			72 2
23	3			73 3
24	4			74 4
25	5			75 5
26	6			76 6
27	7			77 7
28	8			78 8
29	9			79 9
30	10	HEADSPACE ✓ .004	✓	80 10 ✓
31	1			81 1
32	2			82 2
33	3			83 3
34	4			84 4
35	5			85 5
36	6			86 6
37	7			87 7
38	8			88 8
39	9			89 9
40	10	HEADSPACE ✓ .004	✓	90 10 ✓
41	1	Seat pin fell out of fire		91 1
42	2	central - replaced		92 2
43	3			93 3
44	4	✓		94 4
45	5			95 5
46	6			96 6
47	7			97 7
48	8			98 8
49	9			99 9
50	10	HEADSPACE ✓ .004	✓	100 10 HEADSPACE ✓ .004

INS. = Inspected w/ bore scope
 Missfire - 2 chamber, lugs

Look at firing pins, extractor
 bolt lugs

ET19846