Remington Arms Co., Inc. Product Service Legal Case #:5394

Case Information

Date Opened(PS) **Date Closed Incident Date** Pre Lit Obsolete RE# **Date Opened** Lit 12/13/2010 12/13/2010 12/10/2010 213760

Customer Information

Business First Name Last Name Street City State Zip Contact Type Age 7602 NE Aquilla Ct. Incident Trevor Walsh Vancouver WA 98682 H 402-415-6879

Incident Information

Repair Est. **Medical Treatment Medical Status** Claims Codes

ΡI

PD Cause:4038 Could Not Duplicate Concern Concern:1007 Fired on Safe Release S

Unknown

C FSR

Customer sent gun in with a note. He stated that gun fires when turned from safe to fire. df

Firearm Information

Model/Ga. SKU Serial Bbl. DOM Mfg. Type CF/BA 700/223 REM A6711727 BV 1/28/1979 n/a Remington

Date Purchased

Original Where Purchased Accessories Owner

WAMMES GUNS BELEFONTAINE BBL THREAD PROTECTOR, HARD N OH

CASE

CONCRN:FSR

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/700/CF/BA

Cash Reim. Date Cash Date Settlement Release of Claims Release Date Reimbursement Settlement APV APV

Per Ilion - Quote to repair under BLM program

Repair/Replacement Repair/Replacement Date Cost \$60.40 1/5/2011

Per Ilion - Could not duplicate concern. Replace TA, clean & test fire under BLM program - Quote. df 1/6/11: Spoke to customer about quote & he mailed a check about a week ago. Cathy D. will be on the look out for it. df

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
Examination	Examiner		B.TRAVIS
	Exam Date		12/13/2010
	Product Type		RF
	Action Type		A
	Assigned To		T.NAGLE
Cause	4038	Could Not Duplicate Concern	CAL. HAS BEEN CHANGED FROM 222 REM TO 223 REM
Barrel	Description		24" 223 REM
	Date Code		BV
	Bore Plugged	False	
	Bulged	False	
	Fired	False	

1	Eindubile Obstantia	· · · · · · · · · · · · · · · · · · ·	
	Fired while Obstructed		1
	Muzzle/Crown Condition	Slightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	SCRATCHES/MARS
	Fore End Condition	Select	
Receiver	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
	Description		STANDARD M/700 BOLT LOCK SAFETY
Safety	Function	Like new; Functioning	
	Sub-Assembly	Non-ISS	
	Lift	Select	.009
Sear	Notch	Slightly Worn; Functioning	
	Tests	Test Fired	False
Feeding Test	Tests	False	
	Condition	Slightly Worn; Functioning	
	Pull	Select	3#
Trigger	Altered	True	SET SCREWS ALTERED
	Sub-Assembly	M/700 Bolt Lock	
Non-Remington Components	Description		BBL THREAD PROTECTOR,HARD CASE

Factory Repair Instructions
(NOTE: Please print and complete this form, and then include it with your firearm.)

(NOTE: Flease print and complete and for	in, and their include it with your meann.)				
Model Number: Ren 700	Serial Number: A6711727				
Are you the original owner?: NO					
Name: Trever Walsh	Date of Purchase: 1991				
Address (no PO Boxes):					
7602 NE AQUILS CT.					
city: Van Couver,	State: WA Zip: 986XZ				
Phone (Daytime): 402 415-6879	Fax:				
E-mail Address: Would like to receive future e-mail updates from Remington.					
Please describe your problem:					
Gun fires when trined from					
a safe to fire.					
Ammunition Information:					
Manufacturer: Kenny Lon	Type: 223 Anno				
Other (i.e. bullet weight/type, spot size, powder):	554 Sp				
	V				
Handload Information:					
Powder Used:	Powder Weight:				
Case/Hull Used:	Primer Used:				
Bullet Type/Shot Size:	Reloader Used:				
Firearms Care (Cleaning and Lubrication):					
Brand of cleaning solution used:					
How often do you clean the bore? (Months or Number of rounds) Every 20 Role					
How often do you clean the action? (Months or Number of rounds) Attend Every Shoct					
How often do you clean the trigger assembly? (Months or Number of rounds) once les u					
Brand of lubricant used:					

BARBER - Kinzer PPS GAL RE 0012741

How often do you lubricate the bore? (Months or Number of rounds)

How often do you lubricate the action? (Months or Number of rounds)

How often do you lubricate the trigger assembly? (Months or Number of rounds)

Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual?

Comments:

When was the last time that your firearm was serviced by a Rémington authorized repairman/gunsmith?

What were the services performed?

Ship your INSURED firearm by either UPS or Parcel Post to:

REMINGTON ARMS CO., INC

ATTN: Arms Service Divison 14 Hoefler Ave - Ilion, NY 13357

🕮 WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE V: IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE ME, ADDRESS (WITH ZIP CODE), TELEPHONE AND



mage in shipping and handling. Preferably, e returned.)

oss or damage.

le the box. Shipments without a proper

ist. Remington is not responsible for purchase insurance from your carrier.

lelines: ...

:: Repairs \$75.00 and under will be completed and returned to you C.O.D. (To avoid C.O.D. Charges, please include your credit card number and expiration date with your gun)

:: For Repairs over \$75.00, you will receive a written estimate detailing the nature of the repair, applicable taxes and shipping. You will have 30 days to approve the repair estimate. Repairs can be paid by check, money order, or credit card (American Express, Discover, MasterCard, or VISA). If you wish, you can expedite repairs over \$75.00 by setting a pre-authorized amount that can be billed to your credit card.

region TPA, chear the Ffire under TSLP for \$ 20.00 + Ship









