BARBER - Kinzer PPS GAL RE 0012970 Remington Arms Co., Inc.

Product Service Legal Case #:5237

Case Information

RE# **Date Opened** Date Opened(PS) **Date Closed Incident Date** Pre Lit Obsolete Lit 211883 11/30/2010 11/30/2010 11/30/2010 X

Customer Information

Business First Name **Last Name** Street City Zip Contact State Age Type Gander Mt Gander Mt 13975 Hall Rd Shelby Twp ΜI 48315 W 586-247-9900 Reporter 6651 Guidford Dr Grzadzinski Shelby Twsp 48316 H 586-246-4969 Incident Gerarld ΜI

Incident Information

Medical Status Claims Codes Repair Est. Medical Treatment

Unknown

ΡI

PD Could Not Duplicate Concern Cause:4038

Concern: 1008 Fired on Bolt Closing

S FSR \mathbf{C}

12/12/10 Per note with rifle, issue with firearm discharging when bolt was closed once recently. Shells double fed once as well. Scoring issues on shells coming out of magazine.cm No parts available for 710, will replace the rifle with a 770 of the same caliber fls.

Firearm Information

Mfg. Type Model/Ga. SKU Serial Bbl. **DOM** 710/7mm Rem Ma 27412 71305275 PA 6/5/2006 11:26:50 AM CF/BA Remington

Where Purchased **Date Purchased** Accessories **Original Owner**

SPORTS SOUTH INC U

Was repaired 11/2007

Ammunition Information - None Defined Other Products Information - None Defined

Settlement

Remington/710/CF/BA

Reim. Date Cash Date Cash Settlement Release of Claims Release Date Reimbursement Settlement APV **APV**

Per Ilion, no parts available, replace with 770 at no charge

Repair/Replacement Repair/Replacement Cost Date

165.00 12/12/2010


12/12/10 Per Ilion, no parts available, order Model 770 7mm Rem Mag in exchange at no charge.cm

Examination[Remington/CF/BA]

Part	Sub-Part	Code	Comment
	Examiner		supry
	Exam Date		11/30/2010
Examination	Product Type		RF
	Action Type		A
	Assigned To		Supry
Cause	4038	Could Not Duplicate Concern	Adjusted outsidd of factory
	Description		24 inch Model 710 7mm Rem Mag caliber
	Date Code		PA
Barrel	Bore Plugged	False	
	Bulged	False	
	Fired	False	
	Fired while Obstructed		

BARE	BERUZKI ZEV PES GAL F	Sightly Worn; Functioning	
	Firing Pin	Slightly Worn; Functioning	
	Shroud	Slightly Worn; Functioning	
Bolt	Face	Slightly Worn; Functioning	
	Handle	Slightly Worn; Functioning	
	Stop	Slightly Worn; Functioning	
	Condition	Slightly Worn; Functioning	
Extractor	Cut Condition	Slightly Worn; Functioning	
	Ext/Eject Test	False	
	Block Condition	Select	
Locking	Lug Condition	Slightly Worn; Functioning	
	Notch Condition	Select	
Massina	Condition	Select	
Magazine	Box Condition	Slightly Worn; Functioning	
	Exterior Condition	Slightly Worn; Functioning	
Overall	Stock Condition	Slightly Worn; Functioning	
	Fore End Condition	Select	
Dansium	Condition	Slightly Worn; Functioning	
Receiver	Bulged	False	
Safety	Description		Model 710
oaicly	Function	Slightly Worn; Functioning	
	Lift	Select	
Sear	Notch	Slightly Worn; Functioning	
		Condition	Abused; Functioning
Pull	Trigger	Select	5.5 lbs
Altered	Tingger	True	set screw positions adjusted outside the factory
Sub-Assembly] .	Other Remington	

File Add Repair BARB BRIT - Kimple RPPS G. File Add Repair BARB BRIT - Kimple RPPS G. FrmREInquiry - Repair Inquiry Repair Number RE00211883 Seriet 71303275 Model 710 Cent. MM REM MAG Produced 05/05/2/ SKU: 27412		laintenance System Location Location 33PM	
ADDRESS INFORMATION Customer Customer Customer Customer Address 1 ATTN CNDY KILBRIDE Address 2 IBDE 5TH ST SUITE 1300 PO Box City SAINT PAUL State MN Zip Code 55101 Country US FFL Cortact / Condition Problems Estimate History / Status Shipping / Billin Date Code User ID Desc1 11/30/2010 B. New valentids Repair Added 11/30/2010 B. Expedite valentids From Check in 11/30/2010 B. Expedite supryll From Product Services 11/30/2010 3. Estimate sprakerd Estimate Update Repair Search	Form Return To C Received From To C Received From To C Received From To From T	ed from 1 2 3 3 3 PM i Lichardon	
supryfil-tuN/Prod frmRepairMar Start ODAS Delition ODAS GEORGE	n DIIOZRAZI da Grand dia colta		2:53 PM。 2回前 [®] (から 内部) 5346 PM





Service Request Service Order # 6906

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00726 14 Hoefler Ave

Ition, NY 13357 Attn: Service Dept

Date Shipped: 11/17/2010

Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 4-38-099-01-7B-02240

Attn: Gun Parts Dept. 13975 Hall Road

Shelby Two, MI 48315

FIREARM INFORMATION:

Manufacturer: Remington Arms Co Inc.

Type:

Serial Number: 71305275

Model:

710

Cal/Ga.: 7mm Rem Ma.

Cased?

DESCRIPTION OF ITEM RETURNED:

Bolt action rifle w/ magazine

REASON FOR RETURN:

Issue with firearm discharging when boit was closed once recently. Shells double fed once as well. Customer is having scoring issues on shells coming out of magazine, and has tried another magazine but did not remedy issue.

ATTENTION VENDOR

Please contact me with any questions or concerns.

Randal Stroud (586) 247-9900

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to:

Gander Mountain Company

Attn: Cindy Kilbride

180 E. Fifth Street Suite 1300

St. Paul. MALEE404

No parts Aum lable
Order m/770 7mm Rem Mag
in exchange at N/C.
TRED 11/30/10

間フ1305275



BARBER - Kinzer PPS GAL RE 0012973

Gunsmith SO# 6906

GM#171 - Utica 13975 Hall Road Shelby Twp, MI 48315 (586) 247-9900 Gunsmith:



* Work Order Copy *

CUSTOM	ER INFORMATION:	
Home #:	(586) 246-4969	Day #:
Name: Address:	Grzadzinski, Gerald 6651 Guildford Dr	
	Shelby Township, MI 4	8316

DATES:	
Acquired:	10/27/2010
Apx Comp:	
Completed:	
Cust. Called:	
Disposed:	

FIREARM/IN	FORMATION			T NATE OF	7-27-7	
Manufacture	r: Remington Arms Co Inc.	Type:	Rifle	Serial Number:	71305275	
Model:	710	Cal/Ga.:	7mm Rem Ma	Firearm Value:	\$0.00	Cased?:□

Description: Bolt action rifle w/ scope & sling

Condition: used

Service Description: Customer having an issue with shells being scored from magazine. Customer has tried another

rmagazine as well. Double feeding once, and also customer says that it fired when he closed

the bolt recently.

en er großneiter aus mit de	LABOR		
UPC	Description		Amount
		Labor Sub Total:	

Labor Notes:

	PARTS	
UPC	Description	Amount
	Parts Sub Total:	

Parts Notes:

* Estimate Only *

Customer must pick up their own Firearm

	TOTALS
	Labor Sub Total:
+	Parts Sub Total:
	Total:
-	Deposit Amount:
	Amount Due:

* Does not include Sales Tax *

The Child Safety Lock Act of 2005 states "it is unlawful for a dealer to sell, deliver, or transfer any handgun to any person, other than another licensee, unless the transferee (buyer) is provided with a secure gun storage or safety device for that handgun." Gander Mtn. will be providing trigger locks to all transferee's (buyer's) for a nominal fee. Transferee's may also supply their own secure gun storage or safety device.





BARBER - Kinzer PPS GAL RE 0012975



Service Request Service Order # 6906

SHIPPED TO VENDOR/STORE:

Remington Repair FFL# 6-16-00726 14 Hoefler Ave

Ilion, NY 13357 Attn: Service Dept

Model:

Date Shipped: 11/17/2010

Phone: (800) 243-9700

RETURN SHIP TO:

Gander Mountain, FFL# 4-38-099-01-7B-02240

Attn: Gun Parts Dept. 13975 Hall Road

Shelby Twp, MI 48315

FIREARM INFORMATION:

710

Manufacturer: Remington Arms Co Inc.

Type:

Serial Number: 71305275

Cal/Ga.: 7mm Rem Ma

Cased?:

DESCRIPTION OF ITEM RETURNED:

Bolt action rifle w/ magazine

REASON FOR RETURN:

Issue with firearm discharging when bolt was closed once recently. Shells double fed once as well. Customer is having scoring issues on shells coming out of magazine, and has tried another magazine but did not remedy issue.

ATTENTION VENDOR

Please contact me with any questions or concerns.

Randal Stroud (586) 247-9900

BILLING INFORMATION:

Please include the service order number on all invoices and correspondence:

SHIP TO ABOVE ADDRESS

Forward all invoices to:

Gander Mountain Company

Attn: Cindy Kilbride

180 E. Fifth Street Suite 1300

St. Paul, MN 55101

買フ1305275



