PrintDisplay	Kinzer PPS GAL RE	0013639				Page I of I
BANDEN -	KIIZEI FF3 GAL KE	Remington	Arms Co., Inc.			
			ct Service			
		Legal (Case #:5158			
Case Information	•					
RE# Date Ope	ened Date Opene 11/18/20	(-)	te Closed	Incident Date	Pre Lit Lit	Obsolete
Customer Information	on					
Type Business	First Name Last Name	Street	City	State Zip Age	Conta	nct
Incident	Bobby McCreary	1654 Old Sen	eca Rd Central	SC 29630	E mccreary519(@yahoo.com
Incident Information	1					
Claims		Codes	Ŕe	pair Est. Medica	l Treatment Me	edical Status
PI						
PD	Cause:4079	Other - Unexa	nined			
S Fired on safety release		Fired on Safe I		Unknown		
С						
in late september. The	ent to Remington.com, i his past weekend while p fty was very hard going	ush the safty to	fire the gun wen	t off. I have since		
Firearm Information	I					
Mfg.	Туре	Mod	el/Ga. Sk	KU Serial	Bbl. D	OM
Remington	CF/BA	7	00/ 854	437 S673220	4 6/11/2010	8:01:42 AM
Date Purchased	Where Purchased		ssories Origina	l Owner		
	ICK S SPORTING GOC	DS/ATL	S.	č		
AĎĹ SŠ			,			
Ammunition Information - None Defined Other Products Information - None Defined Settlement Remington/700/CF/BA						
Cash Reim Date Cash Date						
Settlement Rele	ase of Claims	Release Date	Reimburser	nent Settlemen		APV
Repair/Replacement Repair/Replacement Cost Date						
11/22/10 Mailing ARS.cm						
Examination[Remington/CF/BA]						
Part	Sub-Part		Code		Comment]
		IL		<u> </u>	Comment	

٠.

Incident - 101108-000243 - Model /00 problem

BARBER - Kinzer PPS GAL RE 0013640 eference # Model 700 problem Reference # 101108-000243

Status Updated Assigned To Administrators Christy -Product Accessories SLA Not specified Queue

CSR

Date Created 11/08/2010 10:11 PM

Initial Response 11/16/2010 10:23 PM

Last Updated 11/18/2010 06:11 PM

Customer SmartSense 0 (on -3 to +3 scale)

Staff SmartSense

+1 (on -3 to +3 scale)

Discussion Thread

Customer (bj mccreary)

My address is 1654 old seneca road central SC 29630. How long is the turn around time? This is my daugther one and only hunting gun. I will be out of town until the 29th. Ican send as soon as I get home. Thanks for your help, Bobby McCreary

From: Remington Information To: mccreary519@yahoo.com Sent: Tue, November 16, 2010 10:23:20 PM Subject: Model 700 problem [Incident: 101108-000243]

Response (Christy -)

rifle would need to ship back to.

Customer (bj mccreary)

5158

11/18/2010 06:11 PM

11/16/2010 10:23 PM Mr. McCreary, I apologize for the delay in responding. I can send you a prepaid UPS ground shipping label for shipment to our factory for a free inspection. Send me the address to mail it to as well as the address the

11/08/2010 10:11 PM

I bought a model 700 adl ss (serial number-S6732204) in late september. This past weekend while push the safty to fire the gun went off. I have since tried to make it do this again with no luck. The safty was very hard going to fire position when the gun went off. Please advise Thanks.

Bobby McCreary

Primary Contact

First Name: bj Last Name: mccreary Organization:

> Login: mccreary519@yahoo.com Title:

Contact Type:

Email: mccreary519@yahoo.com

Email - Alternate #1: Email - Alternate #2:

> Office Phone: **Mobile Phone:** Fax: **Assistant Phone:**

Home Phone: Street City State/Province **Postal Code** Country

Additional Information

56732204

Remington.

www.remington.com

Remington Arms Company, Inc. 870 Remington Drive P. O. Box 700 Madison, NC 27025-0700

ARS LABEL REQUEST FORM

DATE:	18-Nov REQUESTED BY:	christy	
QUANTITY:	1 WEIGHT PER PACKA	GE:	10
PLEASE CHECKONE			
MEDIA			
COORDINATOR TO MAIL	I WILL MAIL	XX	
DESCRIPTION:			
DESCRIPTION.	700		

LABEL INFORMATION

MAIL LABEL TO:	Bobby McCreary 1654 old seneca road central SC 29630
RETURN ITEM TO	: Rem Prod Serv

PLEASE COMPLETE ALL PARTS OF THIS FORM AND SEND TO THE MEDIA COORDINATION

4XX596 NOV 19, 2010 ALL CURR USD SVC GNDCOM ACT WT 10.0 LBS TRACKING# 1Z4XX5969066179821 1 OF 1 REF 1: BOBBY MCCREARY/CD/CM REF 2:700 HANDLING CHARGE 0.00 SVC T/P USD SINGLE-PIECE PUB RATE CHRGS: COD RS 0.50 0.00 DV 0.00 DC 0.00 0.00 SD 0.00 DGD SP 0.00 0.00 AH 0.00 PR PUB+HANDLING 8.74 TOT PUB CHG 8.74