

GUN # A-13

SERIAL # 71147083

CAL: 300 WIN MAG

M710 MAGNUM TRIAL PILOT TEST

TRACKING # TLW 1303

PROJECT # 241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS RDS. FIRED	AT START-0 TOTAL RDS.
SW/PA	12/19/03	Out of box Inspection	TLW1303A		
JS	12-22-03	Detorque Scope crossbolt screws	Front 25 Rear 25		
BL	12-22-03	Headspace	min +.004		
BL	12-22-03	Proof	OK	1	1
BL	12-22-03	Headspace	min +.004		
JS/BL	12-22-03	Depth Take down Screws	habe		
BL	12-23-03	Firing Pin Indent	.021 - .012 - .020 Avg. .020		
JS	12-29-03	Gear/Trigger Engagement	Avg. .0273		
JS	12-29-03	Gear lift	.0142		
SW/JS	1-13-04	Change out Bolt Head			
SW/JS	1-13-04	Headspace	Min +.006		
SW/JS	1/13/04	Proof Rd		1	2
SW/JS	1/13/04	Headspace after proof	Min +.006		
JS	1-14-04	200 Rd. Basic Jack function test	shot clean; Magazine was bent on first side	200	202
SW	1-15-04	Headspace	Min +.006		
JS	1-16-04	Shoulder Function test	X20 Rds. shot clean	20	222
JS/BL	1-19-04	Clean & Inspect	See Inspection sheet		

Logform

BARBER - 5.22.06r0003615

Confidential - Submitter is 22706r0003615 Order

Williams v. Remington

ET19994

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-13

TLW #: TLW1303

Date: 01 / 19 / 04Inspector: JS/BLRound Level: 222☒ Measure Headspace min+.006☒ Sear Engagement: 1st. .0267 2nd. .0262 3rd. .0273Ave. .0267 spec. .020" to .025"☒ Trigger Pull: 1st. 3.967 2nd. 3.772 3rd. 3.832Ave. 3.857

spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.☒ Inspect extractor & bolt face area.☒ Inspect cam surface, locking lugs and bolt stop for signs of excessivewear: Bolt stop is worn, some wear on locking lugs☒ Inspect stock for any signs of cracking or other failure.☒ Other items ofnote: magazine box is protruding - receiver insert has a defect must be in the mold.

TLW1303

Remington Confidential

ET19995