

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Trial & Pilot Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-11

TLW #: TLW1303

Date: 01 / 19 / 04

Inspector: JS / BL

Round Level: 222

☒ Measure Headspace min+.004

☐ Sear Engagement: 1st. 2nd. 3rd.

Ave. spec- .020" to .025"

☐ Trigger Pull: 1st. 2nd. 3rd.

Ave. spec- 4 lb. to 5.5 lb.

☒ Check Take-Down Screws and Re-tighten if necessary.

☒ Inspect extractor & bolt face area. extractor lots of wear and possible broken

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: locking lugs has some wear

☒ Inspect stock for any signs of cracking or other failure:

☒ Other items of

note: magazine Box is protruding, receiver insert has a defect must be the mold.

Couldn't do engagement or trigger Pull, Mike Keeney took bolt head for evaluation

TLW1303

Remington Confidential

ET20129