

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Extruded Receiver "Magnum Caliber"

Project: 241314

TLW #: TLW1689

Date: 2 122 105

Gun Test # A24

S/N 712.02755

Round Level: 721

Inspector: B. LEE

- ☒ Measure Headspace min .004
- ☒ Check Takedown Screw Torque @ Disassembly: Frt 5, Center 20, Rear 5
- ☒ Sear Engagement: 1st .0304 2nd .0247 3rd .0287 Ave. .0286 spec- .025" to .030"
- ☐ Reset Sear Engagement if Required: 1st 2nd 3rd Ave.
- ☒ Trigger Pull: 1st 5.325 2nd 5.303 3rd 5.319 Ave. 5.352 spec- 4.5 lb. to 6 lb.
- ☐ Reset Trigger Pull if Required: 1st 2nd 3rd Ave.
- ☒ Inspect Firecontrol Insert for any signs of cracking or other failure. O.K.
- ☐ Other items of note:
- ☐ Torque Takedown Screws @ Reassembly: SPEC- Frt- 75 in lbs, Center- 30-35 in lbs, Rear- 15 in lbs.

TLW1216

Remington Confidential

ET21848