

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 Magnum

Project: 241314

Rifle: A-9

TLW #: TLW1216

Date: 8 / 20 / 03Inspector: SW/BLRound Level: 221☒ Measure Headspace min + .007☒ Sear Engagement: 1st. .0248 2nd. .0251 3rd. .0250 Ave. .02496 spec- .020" to .025"☐ Reset Sear Engagement if Required: 1st. 2nd. 3rd. Ave. ☒ Trigger Pull: 1st. 4.065 2nd. 4.076 3rd. 3.958 Ave. 4.033 spec- 4 lb. to 5.5 lb.☐ Reset Trigger Pull if Required: 1st. 2nd. 3rd. Ave. ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear: Wear on Bolt stop☒ Inspect stock for any signs of cracking or other failure. Lower corner of recoil bracket has cracks on stock
Crack on middle take down screw hole.☒ Other items of note: Bolt stop does not Lock bolt in place, Top of magazine has
Some protrusion, wear in magazine latch area

TLW1216

Remington Confidential

ET22334