

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Model: 710 Magnum

Project: 241314

Rifle: A-7

TLW #: TLW1216

Date: 8 / 20 / 03

Inspector: SW/BL

Round Level: 221

- ☒ Measure Headspace min +.001

- ☒ Sear Engagement: 1st. .0231 2nd. .0234 3rd. .0235 Ave. .0233 spec. .020" to .025"

- ☐
- Reset Sear Engagement if Required:**
- 1
- st
- . _____ 2
- nd
- . _____ 3
- rd
- . _____ Ave. _____

- ☒ Trigger Pull: 1st. 5.626 2nd. 5.643 3rd. 5.550 Ave. 5.606 spec- 4 lb. to 5.5 lb.

- ☒
- Reset Trigger Pull if Required: 1
- st
- . 4.336 2
- nd
- . 4.418 3
- rd
- . 4.386 Ave. 4.380

- ☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive wear:

- ☒
- Inspect stock for any signs of cracking or other

failure. Lower corner of recoil bracket has cracks on stock
Crack on middle take down screw hole.

- ☒ Other items of

note: Top of magazine Box has some protrusion, wear in magazine latch area

ET22384