

GUN # A-6

SERIAL # 71126322

CAL 300 WIN MAG

DAT # 1 M/ 710 MAGNUM PRODUCTION RECEIVER INSERT

TRACKING # TLW1216
PROJECT #241314

NAME	DATE	TEST ACTIVITY	COMMENTS	ROUNDS RDS. FIRED	AT START-0 TOTAL RDS.
SW/BL	7/21/03	Head space	Min +.004		
SW/BL	7/21/03	Head space	Shoulder Gauge .021 will not close up.		
SW/BL	7/21/03	Firing Pin Indents	.020 - .020 - .020 Avg. .020		
SW/BL	7/22/03	Trigger Pull	4.918, 4.919, 4.972 Avg. 4.936		
SW/BL	7/22/03	Sear/Trigger Engagement	.0290, .0290, .0291 Avg. .02903		
SW/BL	7/22/03	Sear Lift	.0230		
SW/BL	7/22/03	Reset Sear/Trigger Engagement	.0236, .0236, .0235 Avg. .02356		
SW/BL	7/22/03	Reset Trigger Pull	5.289, 5.317, 5.172 Avg. 5.199		
SW/BL	7/22/03	Firing Pin Head / Sear Engagement	.061		
SW/BL	7/23/03	Safety ON Forces	5.275, 5.665, 5.555 Avg. 5.498		
SW/BL	7/23/03	Safety OFF Forces	2.045, 1.930, 1.895 Avg. 1.957		
SW/BL	7/24/03	Bolt Lift	18.80, 17.46, 17.40 Avg. 17.88		
SW/BL	7/24/03	Bolt Close	6.30, 6.56, 6.06 Avg. 6.30		
SW/BL	7/24/03	Bolt Lift w/ Dummy	18.66, 18.04, 17.94 Avg. 18.22		
SW/BL	7/24/03	Bolt Close w/ Dummy	6.64, 6.28, 6.88 Avg. 6.60		
SW/BL	7/25/03	Magazine Spring Force	gauge 0.200 (1.560 - 1.500 - 1.390 - Avg. 1.483		
			gauge 1.0 (4.955 - 5.105 - 5.640 Avg. 5.246		
SW/BL	7/29/03	Magazine Capacity Test	pass - weak ejection		
SW/BL	7/29/03	Check ISS system	PASS		
SW/BL	7/29/03	Twist Rate	1 turn 10" +.25		
SW/BL	7/30/03	Bore diameter	Spec .300/.301 Dimension .300		
SW/BL	8/6/03	Proof Test	Hammer bolt back		
SW/BL	8/6/03	Head space After Proof	Min +.006		
SW	8/7/03	Basic Jack Function Test	1 Malfunction	200	201
Brzin R	8/12/03	Basic Shoulder Functions Test	1 Malfunction	20	21
			1 - Did not bring bolt back all the way.		
SW/BL	8-20-03	Cleaned			
SW/BL	8-20-03	Inspection	Head space min +.006		
SW/BL	8/33/03	Accuracy Test	20 Rds No Malfunctions		
SW/BL	9/5/03	Extended Function	Endurance Test - Total malfunctions 0	20	241
BL	9/8/03	Cleaned		500	741
SW/BL	9/8/03	Inspection	Head space Min +.007		
BL	9/8/03	Magazine Change	Changed magazine Box A-6 to A-11 and A-11 to A-6		
SW/BL	9/10/03	Extended Function	Endurance Test TOTAL malfunctions 11 ETE - 11 ETE EXTRACT		
			Extractor is not extracting empty cartridges from Chamber	500	1141

Logform

BARBER - 5.22.06/0005423

Confidential - SW/BL 7/22/06/0005423 Order

Williams V. Remington

ET22423