

CONFIDENTIAL

Remington Arms Company Inc.
Research & Development Technical Center
315 West Ring Road
Elizabethtown, KY 42701

Clean & Inspect Checklist

Model: 710 EXTRUDED RECEIVER

Project: 241230

Rifle: A-15

TLW #: TLW1530

Date: 9 / 2 / 04Inspector: SWRound Level: 1721
☒ Measure Headspace Min + .006
☒ Sear Engagement: 1st. .0334 2nd. .0333 3rd. .0333
Ave. .0333 spec. .020" to .025" 83
☐ Reset Sear Engagement if Required: 1st. _____ 2nd. _____ 3rd. _____

Ave. _____

☒ Trigger Pull: 1st. 5.46 2nd. 5.38 3rd. 5.47
Ave. 5.40 spec. 4 lb. to 5.5 lb.
☐ Reset Trigger Pull if Required: 1st. _____ 2nd. _____ 3rd. _____

Ave. _____

☒ Inspect cam surface, locking lugs and bolt stop for signs of excessive
wear: locking lugs normal wear, bolt stop little wear
☒ Inspect stock for any signs of cracking or other
failure. still cracked - no worse
☒ Other items of
note: OK

TLW1216

Remington Confidential

ET23044