

April 1, 1947

TO:

FROM:

SUBJECT:

have been subjected to final inspection during the following inspection in accordance with the requirements of the Inspection Chart.

1. Functioning

- a. Action - Green in Trigger. Trigger Pull - 3 lbs. 6 oz. which is below min.

2. Bolt (Visual)

- a. Bolt-Ping - Color does not match Receiver. Rough machine marks.
b. Bolt Head - Rim at inlet of Bolt Head rough.