

REMINGTON ARMS COMPANY, INC.

INTER-DEPARTMENTAL CORRESPONDENCE

Remington

PETERS

Bridgeport, Connecticut, August 27, 1948

TO:

H. A. BROWN  
ILION

FROM:

G. O. CLIFFORD

SUBJECT:

MODEL 721

As a result of some recent complaints of eye injuries with the Model 721 Rifle apparently due to blown primers, it has been asked whether a gas leak might occur as a result of firing the weapon without properly cleaning grease out of the bore. If you have not conducted such a test, will you please make a test firing of a Model 721 with the bore clogged with grease and report the amount of gas leakage at the breech, if any.

*Gee*  
\_\_\_\_\_  
Technical Director

GOC:MR

*Don, Wayne is already aware of this request. - SMA*