

AMMUNITION		Shooter		No. of Rds.		MALFUNCTIONS												REMARKS											
PREVIOUS 2,000 RDS						Firing	Extraction	Don't Blow Back	Ejection	Locking Open	Feed from 1st Mag.	Feed from 2nd Mag.	Double Feed	From Magazine	Dropped Shell	Failed to Trip Carrier Latch	Stem Carrier	High	Low	Rt.	Stem Chamber	Locking Up	Loading	Breakages	Replacement	Gun Failure	Adjustments		
END REMARKS REM. RDS SP	FG	2050																											
"	FG	100																											OK
"	FG	150																											OK
"	FG	200																											OK
"	FG	250																											OK
"	FG	300																											OK
"	FG	350																											OK
"	FG	400																											OK
"	FG	450																											OK
"	FG	500																											OK
"	FG	550																											OK
"	FG	600																											OK
"	FG	650																											OK
"	FG	700																											OK
"	FG	750																											OK
"	FG	800																											OK

DATE 3/18/52 MODEL 721 CAL. 40A. 30.06

GUN NO. 396942

Sheet No. 5

DESCRIPTION OF TEST: QUALITY PROVT TEST

Total Rds. Fired _____
Total Malfunctions _____
Rate _____