bcc: Bill Wagman, Williams Gun Sight Co. Davison, Michigan W.C. Schrader

1 100 CC

and the second second

R. L. St. John

May 22, 1964

Reinhart Fajen, Inc. Warsaw, Missouri

Dear Sir:

. . . .

One of our field representatives recently described the proposed restocking of the Remington XP-100 Pistol with one of your wood stocks. As we understand it there is no provision to accommodate the trigger balance in the stock. Therefore if custom gunsmiths attempt to restock this pistol and omit the trigger balance it will certainly jeopardize the safety of the firearm. I am sure that you would want to avoid becoming involved in the event of any accidents.

Frankly, we are not too familiar with the problem since have not seen one of your stocks for this pistol. However, we would be very glad to make any suggestions if have an opportunity of looking at one.

a construction with the second state of the second state of the second state of the second state of the second

Very truly yours,

S. M. Alvis Ilion Research Division

SMA:T