

Franz, Scott

From: Franz, Scott
 Sent: Monday, November 20, 2000 11:39 AM
 To: Bristol, II Ronald H.; Russo, Al; Trull, John C.; Golemboski, Matt R.; Zajk, Joseph J; Diaz, Danny; Keeney, Mike; Danner, Dale; Snedeker, Jim; Reesor, Phillip K.; Franz, Scott
 Subject: RE: M/710 T & P Issues
 Importance: High

One more topic to add to the list.

1. • ✓ ISS System - could move ISS from "On" to "Off" with a screw driver (1 gun), *detent sticking, sometimes works, sometimes doesn't,*

From: Franz, Scott
 Sent: Monday, November 20, 2000 10:46 AM
 To: Bristol, II Ronald H.; Russo, Al; Trull, John C.; Golemboski, Matt R.; Zajk, Joseph J; Diaz, Danny; Keeney, Mike; Danner, Dale; Snedeker, Jim; Reesor, Phillip K.; Franz, Scott
 Subject: M/710 T & P Issues
 Importance: High

The following topics will be discussed in detail during the 4:00 pm conference call today.

- ✓ Trigger Pull - Toward high side of spec. *3 just out, but not enough to worry about*
- ✓ Engagement High - As measured by E-town, different methods *9% projected out on high side*
pted screw deforming trigger?
gate location? (close)
- ✓ Grip Caps - Falling out during shooting *(6) of 14 Guns at varying rds., 67 rds.*
- ✓ Scope Issues -
 1. ✓ Fuzzy optics on some scopes *1/10 Bushnell (.925) lbs. w/ rings*
 2. ✓ Crosshairs rotated approx. 30 deg. on 1 scope *Swampski (.965) lbs. "*
- ✓ Box bottoms - Falling off during shooting *(3) at 62 rds. 322, 470*
- ✓ Magazine followers - Sticking in box (cause of stem low malfunction) *(3) x 100 rd level*
- ✓ Safety in Fire Position as received - 1 of 30
- ✓ "Pillar bedding" on hang tag - *should be removed*
- ✓ Box removal difficult - varies *works, more rds, more de for,*
- ✓ Bolt Stops Loose - detent force varies
- ✓ Trigger position relative to trigger guard - side to side
- ✓ Take down screws - loosening during shooting
- ✓ Scope rail deformation - *Swampski scope a major factor (2x w.t. of Bushnell)*
Wrist than DAT but?

The topics in red are classified as potential show stoppers. These effect function and short term customer perception. We will discuss all topics in more detail at 4:00 today.

- INDENT Avg .0175" (Saami Min (.017") 4/29 out
- Box fell down 3 times on 1 gun (was it fully latched?)

367, Dale to Call Al for conf