DRAFT

Dear Gun Owner:

This letter will confirm receipt of your telephone call to our toll-free number regarding the recall of certain Remington bolt action rifles and pistols. We would appreciate your checking the following list to verify that your gun is involved:

RECALLED GUNS

All Remington Model 600's .

All Remington Model 660's

All Mohawk 600's - except those with a serial number starting with an "λ".

All XP-100's, with a serial number below 7507984, except those with the prefix "A" or "B" before the numbers.

Remington recommends that prior to any further usage of guns included in the recall, they be inspected - and modified if necessary. If you do not already have the name and address of the nearest Remington Recommended Gunsmith (who will perform the inspection and modification service free of charge), phone one of the following numbers:

In all states except Connecticut (toll free): 1-800-243-2870

In Connecticut (toll free): 1-800-972-9379

The operator will need the model and serial numbers of your gun

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix "A" or "B" before the number.

Owners of the above guns should contact one of the following gunsmiths:

In Anchorage Howard's Gun Shop 528 Fifth Avenue (907) 272-4570

In Anchorage Bill's Gun Shop 8729 Lake Otis Parkivay Anchorage, Alaska 99501 Anchorage, Alaska 99507 Fairbanks, Alaska 99701 (907) 349-1312

In Fairbanks Dixon's 261 College Road (907) 456-8742

If the location of the nearest gunsmith is not convenient for personal delivery of your gun, you may send the gun collect to the gunsmith and have it returned prepaid. Guns covered by the recall should be inspected and modified before further usage. This work will be done at no charge by participating gunsmiths.

approved Versun

IMPORTANT MESSAGE TO OWNERS OF REMINGTON MODEL 600 AND 660 RIFLES, MOHAWK 600 RIFLES, AND XP-100 PISTOLS.

Under certain unusual circumstances, the safety selector and trigger of these firearms could be manipulated in a way that could result in accidental discharge.

The installation of a new trigger assembly will remedy this situation. Remington is, therefore, recalling all Remington Model 600 and 660 rifles, and all Mohawk Model 600 rifles—except those with a serial number starting with an "A."

Also-included in the recall are any XP-100 pistols with a serial number below 7507984, except those with the prefix."A" or "B" before the number.

Remington recommends that prior to any further usage of guns included in the recall, they be inspected - and modified if necessary. To obtain the name and address of the nearest Remington Recommended Gunsmith (who will perform the inspection and modification service free of charge), phone one of the following numbers:

In all states except Connection (toll free):

1 000-243-2070 800-241-8444 — Osle for Opening [] Jesusia In Gomecticus (toll free):

> 2-800-972-9379 800-282-1333-022 for 0 joints 51

In Canada (collect):

519-621-7271