

Rev. 2-15-61

P.I. YES GUN EXAMINATION REPORT NUMBER: 528 MODEL: 700
 GENERAL CONDITION: FAIR R #: 23771
 OUTSIDE WORK: SIGHT REMOVED, RECOIL PAD AND DATE: 10-2-81
SWIVEL STUDS ADDED FROM: CAL REDDICK
920 W. LAKE CANNON L
WINTER HAVEN FLA
 FIRE ARMS TYPE: NOT KNOWN GUN #: 359092
 & CONDITION: _____ CODE: OR-7-68
 PROOF: PEP INSP.: 9 TEST: 55 GA./CAL.: 3006
 HEADING: OK CHECKED BY: M. HARDY
 BREACH OPENING: OK APPROVED: 9/24/81
 RECOIL SHOULDERS: OK APPROVED: PEP 10/12/81
 CHAMBER: OK APPROVED: P. H. 10/21/81
 TEST: _____ APPROVED: JWB 10/22-81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 10/12/81
BOLT RUSTY BRIGHT METAL ON BBL.
MARS ON STOCK, 2 1/2 LB. TRIG PULL

COMPLAINT: FIRED WHEN SAFETY IS RELEASED.

INCIDENT: _____

COMMENTS: Unable to duplicate customer complaint.
Gun passes trick test, .008" vertical rear lift -
.017 Trigger connector engagement.

Trigger adjusting screws adjusted outside factory
as evidenced by red glue on these screws. Trigger pull
2 1/2# - Rem S&W 3# to 5#

Could not follow down on slamming bolt.