

Rev. 2-15-61

P.I. NO GUN EXAMINATION REPORT NUMBER: 500 MODEL: 700 BDL
 GENERAL CONDITION: GOOD R #: 19506
 OUTSIDE WORK: SCOPE BASE ADDED DATE: 7-30-81
 FIRED AMMO TYPE: NOT KNOWN FROM: H.G. BENTLIN
 & CONDITION: 2646 JACOBSON DR.
FALLS CHURCH VA
 GUN #: 223209
 PROOF: (RFP) IMP.: 9 TEST: 87 CODE: ON-7-66
 HEADING: OK GA./CAL.: 243
 BREACH OPENING: OK CHECKED BY: M-HARDY
 RECOIL SHOULDERS: OK APPROVED: 9/1/81
 CHAMBER: OK APPROVED: 9/1/81
 TEST: OK APPROVED: 9/1/81
 COMPONENT CONDITION: (Damaged, Broken, Old Style) APPROVED: 9/1/81

OLD STYLE FIRE CONTROL. SLIGHT DENTS IN WOOD

COMPLAINT: FIRES WHEN SAFE IS RELEASED, AT TIMES

INCIDENT: _____

COMMENTS: Sear-safety cam sticks in downward position,
because of accumulation of dirt & oil. Clean & return
to customer. Clean bolt & firing pin hammer, which
can't be it also.

Send new instruction manual to customer.